

326 Field Hospital
PIN: 903326
C/o 56 APO

226/HS/SMO/2022

10 Oct 2023

APS Damana
c/o 56 APO
PIN-181204

WATER HYGIENE CERTIFICATE

1. Pl ref your office letter No C2/APSD/Gen dt 04 Sep 22.
2. The bacteriological examination report of Pump house APS Damana is fwd herewith as per Appx.
3. For your info and necessary / action pl.




(Harspeet Jutla)
Capt
OIC Health Section
For SMO



REQUEST FOR WATER TESTING
(326 FIELD HOSPITAL)

1. Sample of water collected from : APS DAMANA
2. The reason for the exact nature of examination required : Bacteriological Exam
3. Date & hour of sample : 14Sep2023 at
4. Nature and location of sources of water : Under Ground Water (MES)
5. Nature & distance of any sources From which an inflow of pollution Appear problem. : NA
6. Geological strata likely to affect the water constituents : NA
7. If the sources be a well:-
 - (i) Depth of the water : NA
 - (ii) Staining : NA
 - (iii) Capping : NA
 - (iv) Covering : NA
 - (v) Started penetrated : NA
 - (vi) Method of raising water : NA
8. If stored surface water, nature of Collecting surface and conditions of storage. : NA
9. Meteorological condition heavy Rainfall / drought. : Clear
10. Any treatment the water has received:-
 - (a) Clarification : Yes
 - (b) Chlorination : NA
 - (c) Softening : NA
 - (d) Boiling : NA

Stn : C/o 56 APO



(Chahat pandey)
Capt
OIC Health Sec
for SMO

